

PHOTO #1: VIEW OF THE UST AREA



PHOTO #2: DISPENSING PUMPS ASSOCIATED WITH THE USTs

THE RECORDS CENTER REGIONS

CH01\PUBLIC\WO\RAC\003\26061.PHO1



PHOTO #3: VIEW OF USTs PRIOR TO REMOVAL



PHOTO #4: PREPARATION FOR UST REMOVAL



PHOTO #5: EXCAVATION OF USTs IN PROGRESS



PHOTO #6: EXCAVATION OF USTs IN PROGRESS



PHOTO #7: VIEW OF THE EXCAVATED AREA



PHOTO #8: COLLECTION OF SOIL SAMPLES IN PROGRESS

CH01\PUBLIC\WO\RAC\003\26061.PHO2



PHOTO #9: VIEW OF PIPING ASSOCIATED WITH THE USTs



PHOTO #10: VIEW OF THE EXCAVATED USTs



PHOTO #11: VIEW OF THE EXCAVATED USTs



PHOTO #12: VIEW OF THE EXCAVATED USTs



















